

## ***Contraindications***

- ◆ History of any skin malignancy
- ◆ Chronic skin conditions/irritated skin (i.e., Urticaria)
- ◆ History of cancer
- ◆ Pregnancy (including IVF)
- ◆ Active collagen or vascular disease
- ◆ High blood pressure
- ◆ Phlebitis and blood-clotting (hematology-related)
- ◆ Recent (less than 6 months) use of Isotretinoin (Accutane)
- ◆ Implantable pacemaker or automatic defibrillator/cardioverter (AICD)
- ◆ Past or present autoimmune illness or disorder
- ◆ Large dental metallic prosthetic implants
- ◆ Multi systemic diseases (diabetes, hypertension, coronary artery disease, renal insufficiency etc.)

## ***Special Considerations***

- ◆ Smoking
- ◆ Alcohol consumption
- ◆ Recent surgical procedures
- ◆ On-going medications
- ◆ Dental metallic structure (i.e., bridge)

## ***Adverse Effects of Treatment***

The use of the Accent Prime system may cause:

- ◆ **Heating sensation or pain** – patient may experience a heating sensation during or just following the treatment, however, such pain is expected to be mild and to resolve within few minutes.
- ◆ **Erythema** – may be present in the treated area and will likely disappear after 24 hours.
- ◆ **Burns** – might occur if the operator does not follow instructions, i.e. energy too high or staying too long with the module's tip on the same spot. If such a burn occurs, it should be treated conventionally.
- ◆ **Dry skin** – may occur at the first 12 hours post-treatment. Usually it will resolve spontaneously within 48 hours. Lubrication with moisturizing cream can be helpful.
- ◆ **Local reddening** – customer may experience erythema and hyperemia during or just following treatment, however it is expected to be mild and to resolve within a few minutes to several hours.
- ◆ **Muscle tension/pain** – may be present occasionally in the treated area and is expected to disappear within 24 hours.
- ◆ **Bruising** – may be presented due to excessive pressure of the module on the skin.